

Using the Krink Mini Sprayer is a trial and error process, results will vary depending on the medium, surface, and desired outcome.

DIRECTIONS:

Start with approximately 1/2 gallon water/paint mixture. Mix paint and water thoroughly in a bucket. Do not mix in Mini Sprayer. We recommend beginning with a 1:1.5 water to paint ratio and adjusting from there. The mixture should be quite thin. We suggest starting with matte black latex paint for its covering power.

Pour paint mixture into Mini Sprayer through a mesh filter screen or sieve (not included) to remove clumps and particles that can clog the Mini Sprayer. Close tightly.

Pump until there is significant resistance in handle. A hissing sound may be heard.

Point nozzle at surface and squeeze handle to spray paint. Turn nozzle in small increments to adjust paint line. If line is uneven, thin paint mixture a bit more.

It is best to spray with consistent high pressure. Continue pumping between sprays. Pump until there is significant resistance in handle.

Pull red valve to release pressure when not in use. A seam may crack under high pressure over an extended period of time.

It is extremely important to keep all parts clean. Wash after every use, inside and out. Flush spray parts by running water through all parts. Small bits of dried paint can easily clog the Mini Sprayer.